Please be aware:

The information on the following sheets represents a preliminary survey of this collection. It may well be incomplete, inaccurate, or otherwise out-of-date. This collection may also be, in part or in whole, restricted against access for reason of privacy or other legal issues. This listing is provided to help researchers find potential sources, and to help MASC track unprocessed materials internally. It is strongly suggested that you contact us directly before making any sort of lengthy trip to MASC to view these.

Due to the nature of the presentation of each guide, it is possible the origin and location of this collection may be unclear from this page. If you need to identify the source but are unable to do so, look for the filename (minus the suffix – e.g. if you're looking at ua1996-04.pdf, then search for ua1996-04) within the following page:

http://www.wsulibs.wsu.edu/masc/finders/ualist.htm

Manuscripts, Archives, and Special Collections Washington State University Libraries <u>mascref@wsu.edu</u> 509-335-6691

Transferred from Facilities Operations to Terrell Library, MASC, 4/1/2013. UA2013-06

Files: Nevada State Bridge

#750, 5263-2010, Nevada State Bridge- paint and repair overpass, 2010

Files: Martin Stadium Tunnel

812D		Martin Stadium access tunnel	1992-93
812D	L66282	Repair to tunnel	1992-93
812D	L66282	Access tunnel- tunnel shoring contract 11738	1994
812D		Reconstruct Martin Stadium tunnel (this was	
		never done)	

Drawings: Martin Stadium Tunnel

812D-G-001	L66282	Martin Stadium access tunnel shoring	4/22/94 job no. 92003
812D-G-002	7803	Reconstruct Martin Stadium tunnel	1996 (never done)
812D-G-003		Martin Stadium access tunnel shoring (this	4/11/94 job no. 92003
		was the fix for the tunnel)	

Intercollegiate Nursing Center Files, #9003 (1985-1999)

		· · · · · · · · · · · · · · · · · · ·
	9003	HVAC remodel powers system
-7719	9003	Computer lab, suite 161
-7719	9003	Remodel suite 161 A-F
-2471	9003	Replace stairwell carpet
-3198	9003	Remodel rooms 220 A,B,C,D
-3258	9003	Estimate for showers in restrooms
-5674	9003	Modification to reception counter in main lobby
-8050	9003	Sidewalk repair
L5647	9003	Room 201 and 214 revisions
-3198	9003	Remodel rooms 220A-C
-5751	9003	Remodel of rooms to locker rooms and estimate for installation of two
		handicap showers
L 46977	9003	Library lighting
L 48049	9003	Remodel room 161G
L 48049	9003	Remodel audiovisual office
L 48049	9003	Remodel room 161G
L 48923	9003	Carpet specifications for room 166
L 48924	9003	Hallway lighting
L 56322	9003	Classroom seating room 148
L 86396	9003	Provide emergency lighting
L 112189	9003	Replace practice lab cubicle curtains and bedspreads
L 139128	9003	Combine portion of room 255 into room 261C
L 116526	9003	New Whets classroom and control room, conference room seats

ICNE Boiler

L 123672	9003	Seating room 156
L 130063	9003	Provide computer work station in library
L 139130	9003	A/C in room 168/170
L 138259	9003	Repaint all interior areas
L 139215	9003	Replace carpet, room 159
L 160559	9003	Carpet for Suite 247
L 162152	9003	Replace carpet in student lounge, room 141
L 171359	9003	Carpet for room 206 and 207
L 173973	9003	Replace worn carpet in priority areas
L 182883	9003	Door opening between rooms 220D and 220E
L 139130	9003	Revise ventilation
L 194491	9003	Provide doorway between rooms 247A & B
L 202054	9003	Room 165 video production
L 258513	9003	Replace boilers
L 43932	9003	Boiler replacement

ICNE Drawings

ICINE Drawings		
L 194491	9003-G-14	Remove wall between rooms 247A and 247B
L 182883	9003-G-13	Provide door opening between rooms 220D and 220E
L 138259	9003-G-12	Painting and carpeting of the interior public areas
L 139128	9003-G-11	Renovation of ICNE rooms 255B and 261C
L 139127	9003-G-10	Install new door operators
L 116526	9003-G-9	W.H.E.T.S. alterations I.C.N.E.
L 48050	9003-G-8	Install new sidewalk to Fort George Wright
L 48049	9003-G-7	Remodel room 161G
L 45751	9003-G-6	Remodel rooms 121D and 121F into room 119
L 45674	9003-G-5	Modification to reception counter in main lobby
L 45342	9003-G-4	Modifications to rooms 168 and 170
L 43198	9003-G-3	Remodel of rooms 220 A,B,C,D
L 7719	9003-G-2	Remodel of room suite 161 A-F
L 5647; drawing.	9003-G-1	Revisions to workroom 201 and lounge 214
no. 6476		
L 10625	9003-M-9	Computer control remodel
6929	9003-M-8	Install dial up temperature controls
6802	9003-M-7	Auto, temperature controls AHV-1 and cond. unit
L 43932	9003-M-6	Installation of new boiler
6180	9003-M-5	Irrigation improvements
6704	9003-M-4	Remodel of room suite 161 A-F (in 9003-G-2)
6475	9003-M-3	HVAC improvements
6470	9003-M-2	Relocate fire hydrants
5649	9003-M-1	Ventilation alterations to workroom 201
L 86396	9003-E-5	Provide emergency lighting
L 48924	9003-E-4	Replacement of 175 watt mercury vapor lighting
L 46977	9003-E-3	Additional light fixtures
7042	9003-E-2	Emergency lighting systems
3322	9003-E-1	Remodel of room suite 161 A-F (in 9003-G-2)